

No	Part	Description	Qty
1	D0210	NVH Interface Quick Start Guide	1
2	PA158	4-NVH carrying case	1
3	TA096	Magnetic mounting for accelerometer	4
4	TA143	MEMS 3-axis accelerometer (Waco)	4
5	TA144	Microphone for NVH kit	4
6	TA145	NVH sensor extension cable, 3 meter (for accelerometer or microphone)	4
7	TA243	BNC cable (50cm) - blue	1
8	TA244	BNC cable (50cm) - red	1
9	TA245	BNC cable (50cm) - green	1
10	TA259	3-output NVH interface	4
11	TA260	BNC cable (50cm) - yellow	1
12	TA512	Mongoose-Plus ISO/CAN3 w/J2534 lead	1

1 **D0210**



2 **PA158**



3 **TA096**



4 **TA143**



5 **TA144**



6 **TA145**




7 **TA243**



8 **TA244**




9 **TA245**



10 **TA259**



11 **TA260**



12 **TA512**

