

No	Part	Description	Qty
1	D0254	Optical Balancing Kit Quick Start Guide	1
2	PA100	Optical Sensor Carry Case	1
3	TA186	Optical Sensor w/8' cable, 3.5mm plug, jam nuts	1
4	TA187	Magnetic base for optical sensor	1
5	TA188	Directional tape measure for propshaft balancing	1
6	TA240	Reflective tape for optical sensor (TA186) - 1/2" X 24	1
7	TA260	BNC cable (50cm) - yellow	1
8	TA284	Optical sensor interface w/batteries	1

1 D0254



2 PA100



3 TA186



4 TA187



5 TA188



6 TA240



7 TA260



8 TA284

